Q

Actual exam question from CompTIA's 220-1101

Question #: 1

Topic #: 1

[All 220-1101 Questions]

SIMULATION -

Laura, a customer, has instructed you to configure her home office wireless access point.

She plans to use the wireless network for finances and has requested that the network be setup with the highest encryption possible.

Additionally, Laura knows that her neighbors have wireless networks and wants to ensure that her network is not being interfered with by the other networks. She requests that the default settings be changed to the following.

Wireless Name: HomeWiFi -

Shared Key: CompTIA -

Router Password: Secure\$1 -

Finally, Laura wants to ensure that only her laptop and SmartPhone can connect to the network.


Laptop: IP Address 192.168.1.100 Hardware Address: 00:0A:BF:03:C4:54 SmartPhone: IP Address 192.168.1.101 Hardware Address: 09:2C:D0:22:3F:11


INSTRUCTIONS -

Configure Laura's wireless network using the network adapter window.

If at any time you would like to bring back the initial state of the simulation, please click the Reset All button.







Actual exam question from CompTIA's 220-1101

Question #: 2

Topic #: 1


[All 220-1101 Questions]

DRAG DROP -

An office manager reports that a printer is experiencing performance issues. Printouts are smudging when they are handled, and, recently, whenever the manager tries to print oversized documents, the paper jams before anything is printed on it.

INSTRUCTIONS -

Using the available printer parts, replace only the faulty components on the office printer to resolve the stated issues. If at any time you would like to bring back the initial state of the simulation, please click the Reset All button. Select and Place:





Q

HOME EXAMTOPICS PRO POPULAR EXAMS VIEW ALL EXAMS DOWNLOAD FREE COURSES CONTACT FORUM

Actual exam question from CompTIA's 220-1101

Question #: 3

Topic #: 1

[All 220-1101 Questions]

DRAG DROP -

A small ISP has hired a new technician. Joe, the new technician, is being trained to configure customers' home networks. The training instructor gives the technician a starter kit with cables, cable ends, and other network equipment and asks him to build a working network.

The computer should be connected to have Internet connectivity and the phone should be connected to have a dial tone.


INSTRUCTIONS -

Use the appropriate cables, cable ends, tools and equipment to configure the network and connect all components accordingly.


There are 2 steps and the simulation starts on step 1.


If at any time you would like to bring back the initial state of the simulation, please click the Reset All button.

Select and Place:



Q





IA C AA

Actual exam question from CompTIA's 220-1101

Question #: 7


Topic #: 1


[All 220-1101 Questions]


While implementing a non-carrier-grade wireless backhaul, a technician notices the current channel selection is extremely polluted with various RF signals. Upon performing a spectral analysis, the technician discovers a channel containing almost no RF pollution. Unfortunately, the technician is unable to select that channel. Which of the following is the MOST likely reason for this issue?


- A. The channel is reserved for licensed band use.
- B. The channel selection is defective; contact the manufacturer.
- C. The channel must be unlocked by the vendor.
- D. The device requires a firmware update to unlock the channel.


Show Suggested Answer














INEAA

Actual exam question from CompTIA's 220-1101

Question #: 24

Topic #: 1

[All 220-1101 Questions]

A user on a SOHO network is unable to watch online videos, even at 240 pixels. The technician runs ipconfig from the user's computer and records the following:

Connection-specific DNS Suffix .: Ian

Link-local IPV6 Address....... fe80::1585:7fb2:b05f:7102%12

IPv4 Address..... 192.168.1.131

Subnet Mask...... 255.255.255.0

Default Gateway...... 192.168.1.1

The technician then connects a test laptop to the router via the user's Cat 5 cable and records the following information:


Download: 85 mbps -


Upload: 22 mbps -


Ping: 28 ms -


Which of the following is MOST likely causing the user's issue?


- A. Incorrect IP address
- B. Faulty NIC
- C. Misconfigured default gateway
- D. Bad network cable











Actual exam question from CompTIA's 220-1101

Question #: 38

Topic #: 1

[All 220-1101 Questions]

A user submits a help desk ticket regarding a smartphone that will no longer accept its charging cable. The assigned technician notices the phone does not have a protective case, and the user constantly transports the phone in a pocket. The technician attempts to use a secondary charger, but the cable falls out of the phone. Which of the following is the MOST likely cause of the issue?


- A. The phone requires a firmware update to address charging issues.
- B. The charge port contains foreign objects, such as lint.
- C. The phone's battery has swelled, preventing the utilization of the charge port.
- D. The phone has experienced water damage, thus the battery is not charging.


Show Suggested Answer


 \sim

FORUM

Q








A user submitted a ticket to report an issue with a new printer that is no longer accepting new print jobs. The technician verifies the printer is on and notices the printer LCD screen has the following error message:

Paper Jam, Jam in Fuser.

Which of the following is the MOST efficient next step the technician should complete?

- A. Apply a maintenance kit to the printer.
- B. Check the printer paper path to locate any obstructions.
- C. Turn the printer on and off to see if the error clears.
- D. Replace the fuser.



Actual exam question from Comp HAS 220-110

Question #: 50

Topic #: 1

[All 220-1101 Questions]

A company has a dot matrix printer that uses carbon paper. The company reports that the first page is printing too light, although the following pages are still legible. Which of the following MOST likely needs to be fixed?

Q

- A. The print drum is worn and loose, causing the printing to be light in places.
- B. The ribbon is low on ink or missing and must be replaced to get proper output.
- C. The heating element has failed, and a new one needs to be installed for proper transfer.
- D. The wrong type of filament is loaded, preventing it from sticking correctly.
- E. The fuser assembly is not calibrated properly, causing it to impact the paper too hard.

Actual exam question from CompTIA's 220-1101

Question #: 52

Topic #: 1


[All 220-1101 Questions]

A technician receives several error alerts on a server after an unexpected reboot. A message states that one or more disks are in a degraded state. When the technician advances to the next error message, it indicates the OS is missing. Which of the following are the MOST likely causes of these errors? (Choose two.)

FORUM

Q

- A. Missing drives in the OS
- B. RAID failure
- C. Bootable device not found
- D. Data loss
- E. Controller failure
- F. CMOS corruption
- G. TPM malfunction



Actual exam question from CompTIA's 220-1101

Question #: 55

Topic #: 1


[All 220-1101 Questions]

An engineer is experiencing unexpected reboots on a graphics workstation when rendering complex 3-D models. The workstation is configured with a 115V power supply that is rated at 200W and connected to a UPS. The central processing unit contains 16 hyperthreaded cores, and a discrete graphics solution utilizing an 8-pin power connector is installed in a PCI Express x16 slot. Which of the following indicates where the technician should begin troubleshooting?

FORUM

Q

- A. The UPS, as 115V is insufficient for the configuration and should be increased to 220V
- B. The power supply, as 200W is insufficient when the GPU is heavily tasked
- C. The graphics card, as it is the component that triggers the unexpected reboots
- D. The motherboard, as only standard PCI slots should be used for high-end graphics cards, not PCI Express slots



COURSES

IN E W

CONTACT

FORUM

Actual exam question from CompTIA's 220-1101

Question #: 57

Topic #: 1

[All 220-1101 Questions]

An end user reports that the time and date on a desktop resets after shutdown, and subsequently, the device reboots. The next day, the desktop does not load the OS and is stuck at a black screen with the following message:

Date/Time Not Set -

Press F1 to Run Setup -


Which of the following would be the BEST action to take next?


- A. Change the motherboard.
- B. Reseat the motherboard power connections.
- C. Replace the CMOS battery.
- D. Restore the BIOS to factory default settings.


Show Suggested Answer


 \sim


- A. Try to set as many pins as possible.
- B. Install an adaptor to create a universal socket.
- C. Verity the socket type and manufacturer.
- D. Find a compatible motherboard for the CPU.























- B. Clean the keyboard.
- C. Reset the BIOS settings to default.
- D. Charge the laptop.







Actual exam question from CompTIA's 220-1101


Question #: 87


Topic #: 1

[All 220-1101 Questions]

A user calls the help desk for assistance configuring an Android phone with a new NFC-enabled speaker that will be used for an upcoming conference call. The user was unable to direct the phone's audio to the NFC speaker. Which of the following sequences should the help desk technician walk the customer through to accomplish this task?

- A. Enable NFC on the speaker. Ensure the speaker is less than 33ft (10m) from the Android phone. On the phone's Bluetooth settings menu for Connected Devices, select Pair New Device. Tap to accept the connection to the speaker when the prompt is displayed on the phone's screen.
- B. Enable NFC and Bluetooth on the Android phone. From the Android phone's Bluetooth settings menu for Connected Devices, select the Previously Connected Devices option. Select a listed device that most closely matches the speaker. Tap to accept the connection to the speaker when the prompt is displayed on the phone's screen.
- C. Enable NFC and Bluetooth on the Android phone. Tap and hold the Android phone to the spot on the speaker where the NFC logo is displayed. Accept the connection to the speaker when the prompt is displayed on the phone's screen.
- D. Enable Wi-Fi on the speaker. Enable Wi-Fi on the Android phone. Tap and hold the Android phone to the spot on the speaker where the NFC logo is displayed. Accept the connection to the speaker when the prompt is displayed on the phone's screen.








error message: no source found

The user tries multiple cables and inputs on the projector. Which of the following should the user try NEXT?

- A. Check the bulb on the projector and replace it with a new one.
- B. Check the display settings on the computer and set them to extend/duplicate.
- C. Replace the projector with another known-good one and try again.
- D. Replace the video card on the machine that is plugged in to the projector, as it has gone bad.







Actual exam question from CompTIA's 220-1101

Question #: 102

Topic #: 1


[All 220-1101 Questions]


A user creates a support ticket to report a conference room projector that does not work. The user says that even though the provided cables are being used, the projector screen shows the following error message:


No Signal Input -


Which of the following describes the FIRST action that should be taken?


- A. Verify that the projector is turned on.
- B. Verify that the user is using an approved OS.
- C. Replace the projector bulb.
- D. Check the video cable and replace it if necessary.

















Q

Actual exam question from CompTIA's 220-1101

Question #: 117

Topic #: 1


[All 220-1101 Questions]


A technician is preparing to set up a gaming computer with the following components:

- Discrete, high-end graphics card
- ⇒ Video capture card
- ➡ High-end processor
- Multiple hard drives
- □ USB 3.0 hub
- Sound card

Which of the following options is the MOST important for the technician to consider before building the gaming computer?

- A. Redundant power supply
- B. Modular power supply
- C. 20-pin vs. 24-pin power adapter
- D. Power supply wattage rating








[All 220-1101 Questions]

A user reports a cell phone is getting hot. Which of the following are MOST likely to be possible causes? (Choose three.)

- A. Using the device as a Wi-Fi hotspot
- B. A cracked screen
- C. A failing battery
- D. Less than 15% free storage space on the phone
- E. Privileged control
- F. Recurring prompts to install OS updates
- G. Granting too many application camera permissions
- H. Too many open applications







IN E W

Actual exam question from CompTIA's 220-1101

Question #: 126

Topic #: 1

[All 220-1101 Questions]

A user reports limited or no connectivity on a laptop. A technician runs ipconfig /all with the following result:

IPv4 connectivity...limited or none

IPv4 address...169.254.254.1 -

subnet mask...255.255.0.0

default gateway...

Which of the following is the MOST likely cause of this issue?

- A. DHCP failure
- B. ARP cache
- C. DNS resolution
- D. Duplicate IP address

Actual exam question from CompTIA's 220-1101

Question #: 127

Topic #: 1


[All 220-1101 Questions]


A Wi-Fi mesh network has been optimized to eliminate poor coverage areas, yet users still experience decreased bandwidth and connectivity issues. Which of the following actions should the technician take NEXT?


- A. Relocate any large, dense, solid, and metal objects, such as mirrors and file cabinets, in the mesh network coverage area to the perimeter so that wireless reflections, absorptions, and occlusions are minimized.
- B. Use a Wi-Fi analyzer to determine whether the channel in use is overcrowded and to identify which channel the mesh network should use for best performance.
- C. Use the signal strength indicator on a mobile device to roam the coverage area and generate a heat map to isolate zones with weak signals.
- D. Turn off broadcasting of the SSID on the mesh network so that other networks cannot see it.


Show Suggested Answer


Q





























- A. Attempt to reinstall the application.
- B. Verify the system functionality.
- C. Test the functionality of the antivirus.
- D. Complete the final report.
- E. Determine the source of the installation file.

Actual exam question from CompTIA's 220-1101

Question #: 152

Topic #: 1

[All 220-1101 Questions]

A technician responds to a help desk ticket that indicates a user's workstation is not booting. The technician initially suspects a failed hard drive. The technician performs diagnostics and confirms the hard drive is fully operational. Which of the following steps should the technician complete NEXT?

- A. Reinstall the operating system.
- B. Configure a new RAID array.
- C. Report the status of the drive and close the ticket.
- D. Consider another possible cause of the issue.
- E. Restore the latest backup of the system.

Show Suggested Answer

^

FORUM

Q

Actual exam question from CompTIA's 220-1101

Question #: 154

Topic #: 1


[All 220-1101 Questions]


A user who works with sensitive data has a computer configured with hard drive encryption. The TPM is active and hosting the encrypted key. After an upgrade to the motherboard, RAM, and video card, the hard drive is not booting, and data cannot be accessed from the hard drive. Which of the following should the technician do to enable the system to boot again and get access to the stored data?


IA C AA


Q


- A. Use data recovery software to find and recover the hard drive information.
- B. Access the BIOS and select to rebuild the degraded RAID array.
- C. Boot into the BIOS and enable the TPM on the new motherboard.
- D. Return the replaced motherboard back to the computer.











IA C AA

Actual exam question from CompTIA's 220-1101


Question #: 167

Topic #: 1

[All 220-1101 Questions]

To control costs, a company provides a limited number of users with company phones. One of these users opens a support ticket because the phone no longer allows Internet browsing over a cellular connection. The user acknowledges that the phone worked before the user's child streamed several movies using the device. Which of the following describes why the phone cannot browse the internet?

- A. The child accidentally connected to a neighbor's WLAN.
- B. The company's group policy disabled the device.
- C. The device has a data cap and has reached that limit.
- D. The device's plan has been unpaid.



Actual exam question from CompTIA's 220-1101

Question #: 171

Topic #: 1

[All 220-1101 Questions]

A new computer was plugged into a port that was used by a legacy network printer prior to the completion of an office remodeling project. The user who was assigned to the new computer has been reporting an issue with slow network speeds. A technician verified the NIC is functioning properly and the drivers are up to date, and then swaps out the Cat 6 patch cable. However, the issue persists. Which of the following troubleshooting steps should the technician take NEXT?


- A. Check the speed and duplex settings on the switch.
- B. Verify which port the VLAN is assigned to.
- C. Ensure settings within the computer's BIOS.
- D. Replace the cable that runs from the user's desk to the patch panel.


Show Suggested Answer


^

FORUM

Q







HOME EXAMTOPICS PRO POPULAR EXAMS VIEW ALL EXAMS DOWNLOAD FREE COURSES CONTACT FORUM

Actual exam question from CompTIA's 220-1101

Question #: 177

Topic #: 1

[All 220-1101 Questions]

H0TSP0T

-

A customer has contacted you about building two new desktops. The first desktop will be a gaming workstation. The customer requirements include:

- · Playing the newest games at a high frame rate
- · Fast game load times
- · Enough storage to have several games installed at once
- · High-end audio
- · No concern about cost
- · Running the current Windows OS

The second workstation will be a family workstation. The requirements include:


- · Capability for word processing, videoconferencing, and basic web surfing
- · Minimal cost, as long as it meets the requirements
- · Running the current Windows OS

INSTRUCTIONS

-

Use the drop-down menus to select the appropriate component for each category, based on the above requirements.

If at any time you would like to bring back the initial state of the simulation, please click the Reset All button.



Q

Q

Actual exam question from CompTIA's 220-1101

Question #: 178 Topic #: 1

HOTSPOT

[All 220-1101 Questions]


A customer built a computer for gaming, sourcing individual components and then assembling the system. The OS starts up, but within a few minutes the machine locks up. The customer brought the computer to a technician to diagnose the issue.


INSTRUCTIONS


Click on each component to view the specification.


Select the appropriate cause and resolution for the issue.

If at any time you would like to bring back the initial state of the simulation, please click the Reset All button.













BIOS











Decrease memory module frequency Replace GPU with lower performance model




[All 220-1101 Questions]

A technician has noticed that a monitored server is receiving a disk failure notice during startup. When the technician clicks to continue, the machine still seems to startup into Windows but at a much slower speed. The technician looks at the BIOS information and sees the machine utilizes a RAID 5 configuration. Which of the following does the technician MOST likely need to perform?

- A. Reinstall the HDD drivers.
- B. Rebuild the RAID.
- C. Replace the failed drives.
- D. Restart the system.





Question #: 184

Topic #: 1

[All 220-1101 Questions]

The IT department issued a corporate smartphone to a user, but the user returned the device stating it had connectivity issues. The user claimed the device functioned on Wi-Fi, but all connectivity to cloud services was lost as soon as the device was taken off site. Which of the following issues was MOST likely affecting the device?

- A. MDM was never properly set up on the device.
- B. S/MIME certificates were corrupted and needed to be reloaded.
- C. Bluetooth on the device was disabled by mistake.
- D. The device never had a proper SIM card installed.

The technician double-checks the bill of materials for the new build and confirms all items have been installed. Which of the following should the technician do NEXT?

- A. Ensure thermal paste is being used on the CPU.
- B. Check to make sure that any video cards have auxiliary power cabling connected.
- C. Verify the header panel connector is properly connected.
- D. Spot-check that the I/O shield for the motherboard is properly installed.

FORUM

Q

Actual exam question from CompTIA's 220-1101

Question #: 186

Topic #: 1

[All 220-1101 Questions]

A user receives the following error when trying to reboot a computer:

System RAID Controller FW v1.2

A disk member in an array has failed or is not responding


Port Device ID Description Status


sata0 disk0 Generic 500 SATA III OK


satal disk1 Generic 500 SATA III Not Found


Which of the following is the MOST likely cause of this error message?

- A. Corrupted bootloader
- B. Faulty RAID controller
- C. Failed hard drive
- D. Incorrect storage device driver














- A. Verify that the printing trays are correctly set
- B. Swap printer trays until the print jobs complete as expected
- C. Replace the tray rollers to ensure proper paper alignment
- D. Reset the default to use 8.5in x 11in (216mm x 279mm) paper




















Actual exam question from CompTIA's 220-1101

Question #: 211

Topic #: 1

[All 220-1101 Questions]

A user reports a monitor, keyboard, mouse, and headset are no longer functioning. The user has restarted the laptop and tested an alternative headset and monitor, but the issue persists. The technician notices the user has a printer, USB-C hub, and AC adapter plugged into the laptop. Which of the following should the technician do to MOST likely resolve the issue?


- A. Verify the AC adapter voltage.
- B. Repair the operating system.
- C. Replace the user's USB-C hub.
- D. Reinstall the drivers for affected devices.
- E. Make sure the printer is not drawing too much power.


Show Suggested Answer


^


FORUM


Q











Actual exam question from Comp I IA's 220-110

Question #: 219


Topic #: 1


[All 220-1101 Questions]

A user has decided to build a new computer with parts purchased from a popular online vendor. The user has referenced online resources to assemble the unit. However, when the user presses the power button, the new computer does not load the operating system's installer. Instead, the onboard speaker beeps and immediately reports an issue on the screen. Which of the following is the MOST likely issue with the new build?

Q

- A. The user did not plug in the processor's fan.
- B. The user did not apply thermal paste to the CPU.
- C. The user did not seat the GPU correctly.
- D. The user did not install the power supply.





DOWNLOAD FREE

IN E VV

Actual exam question from CompTIA's 220-1101


Question #: 226


Topic #: 1

[All 220-1101 Questions]

A user's Windows computer started running slowly after the installation of a CAD program. The computer has intermittent timeouts and often has to be rebooted to restore functionality. The computer seems to work correctly if the application is not running. Which of the following should the technician do NEXT to help troubleshoot the issue? (Choose two.)

- A. Replace the video card.
- B. Research the requirements of the application.
- C. Install a new case fan.
- D. Run chkdsk on the HDD.
- E. Check the Event Viewer logs.
- F. Reinstall the application.





Q

Actual exam question from CompTIA's 220-1101


Question #: 231

Topic #: 1

[All 220-1101 Questions]

The owner of a restaurant reports that wireless network connections are lost intermittently throughout the day. Which of the following steps should a technician take to troubleshoot the issue? (Choose two.)

- A. Identify the location of devices that utilize 2.4GHz.
- B. Check to see if the phones are UTP or STP lines.
- C. Test to see if the copper electrical wires are causing interference.
- D. Map all of the wireless signals in the restaurant.
- E. Verify T568B is being used in the wiring closet patch panel.
- F. Schedule timed router reboots throughout the day.



HOME EXAMTOPICS PRO POPULAR EXAMS VIEW ALL EXAMS DOWNLOAD FREE COURSES CONTACT FORUM

IAC AA

Actual exam question from CompTIA's 220-1101

Question #: 234

Topic #: 1


[All 220-1101 Questions]


A network administrator is troubleshooting a connectivity issue. The administrator performs a port scan, and the following information is generated:


Port Number	Status
22	Open
53 80	Closed
80	Closed
1443	Open
443	Closed
3389	Closed
445	Closed


Which of the following standard ports should be open to allow a successful RDP connection?


- A. 53
- B. 443
- C. 445
- D. 3389




























- A. The internal antennas are connected.
- B. The device has the latest OS updates.
- C. The wireless device drivers are the latest version.
- D. Airplane mode is disabled.
- E. The battery is charging.







































































- A. The boot partition is not set as active.
- B. The BIOS does not have NVMe boot drivers.
- C. The NVMe drive has an MBR partition.
- D. The NVMe drive is out of space.

Show Suggested Answer







Q

Actual exam question from CompTIA's 220-1101


Question #: 292


Topic #: 1


[All 220-1101 Questions]

A field technician for an airport receives a support ticket that states customers are having issues viewing a screen that displays information about departing flights. While checking the case history, the technician sees that all fight information screens were recently moved when the terminal gates were remodeled. Which of the following actions should the technician perform after verifying the screen has power?

- A. Ensure the input connections to the screen are secure.
- B. Swap cables with a screen that works.
- C. Check to see if the device outputting the data is turned on.
- D. Determine if the screen is compatible with the output device.







IN E VV

Actual exam question from CompTIA's 220-1101


Question #: 297


Topic #: 1

[All 220-1101 Questions]

A user calls the help desk about a 4K monitor that will not output an image from a desktop. The monitor was working previously but now shows a black screen with a message stating a signal is not detected. The desktop is connected via HDMI, and the monitor has an empty DVI port. Which of the following steps should the technician perform FIRST? (Choose two.)

- A. Check the version of the HDMI cable.
- B. Check the input source.
- C. Set up the desktop for DVI.
- D. Replace the HDMI cable.
- E. Install OS updates.
- F. Initiate a system restore.





Actual exam question from CompTIA's 220-1101

Question #: 305

Topic #: 1

[All 220-1101 Questions]


A systems administrator is attempting to resolve a ticket regarding an issue with an email server. The administrator is covering for a coworker who was previously working on the ticket. The coworker already gathered facts about the issue and spoke with users concerning their missing emails. The coworker also discovered the email server's retention policy was updated shortly before users first noticed the issue. Which of the following should the systems administrator do NEXT to resolve the email issue?


FORUM


Q


- A. Escalate the ticket to a higher level to resolve the email server issue.
- B. Test a theory to determine the cause of the email server issue.
- C. Establish a theory of probable cause for the email server issue.
- D. Create a plan of action to resolve the email server issue.

- A. Hybrid cloud
- B. Infrastructure as a service
- C. Public cloud
- D. Private cloud









Question #: 312

Topic #: 1

[All 220-1101 Questions]

Using the output below:

IPv4 Address: 172.25.1.39 -

Subnet Mask: 255.255.255.0 -

Router: 172.25.1.252 -

Name Server: 172.25.1.4 -

Which of the following is the default gateway?

- A. 172.25.1.252
- B. 172.25.1.39
- C. 172.25.1.4
- D. 255.255.255.0

Actual exam question from CompTIA's 220-1101

Question #: 318

Topic #: 1

[All 220-1101 Questions]

A user is unable to access the internet on a PC. A technician examines the PC and runs the following commands:


ipconfig /all


ping 8.8.8.8


ping comptia.org


Which of the following steps in the troubleshooting process does this series of commands represent?

- A. Establish a theory.
- B. Verify full system functionality.
- C. Establish a plan of action.
- D. Identify the problem.









Actual exam question from Comp HAS 220-110

Question #: 330

Topic #: 1

[All 220-1101 Questions]

The motherboard on a user's company laptop was recently replaced. Now, the user is unable to log in using the fingerprint reader. The fingerprint reader is working, but it does not recognize the users fingerprint. Which of the following should a technician perform FIRST to fix the issue?

- A. Restore the system to a previous recovery point.
- B. Reinstall the fingerprint software.
- C. Access the BIOS and clear the TPM.
- D. Update the drivers and the fingerprint software.
- E. Flash the newest BIOS firmware that is available.

Show Suggested Answer

^

Q

Actual exam question from CompTIA's 220-1101

Question #: 331

Topic #: 1


[All 220-1101 Questions]


A user is experiencing an issue when trying to use a camera on a corporate mobile device to take pictures. The camera on the device is working. However, when the user tries to access the pictures via a USB cable connected to a PC, the user is unable to copy the pictures to the PC. Which is the following BEST describes the likely cause of the issue?


Q


- A. Settings are preventing the transfer of data from the device's camera.
- B. A technician needs to change the camera settings on the device.
- C. The device has corrupted picture files due to an update.
- D. The device needs to have the OS reinstalled.

Show Suggested Answer









Actual exam question from CompTIA's 220-1101

Question #: 342

Topic #: 1

[All 220-1101 Questions]

A user reports intermittent connectivity. The technician checks the network logs and sees the following output:

Interface 0/1 Status Up 13:01:30 Interface 0/1 Status Down 13:02:30 Interface 0/1 Status Up 13:03:20 Interface 0/1 Status Down 13:04:10 Switch elected as Root bridge Interface 0/1 Status Up 13:05:40

Which of the following is the most likely reason for this issue?

- A. External interference
- B. High latency
- C. Jitter
- D. Port flapping

Show Suggested Answer

 \sim

